

## CHECKLIST FOR INSPECTION OF BIORETENTION SYSTEM/TREE FILTERS

Location: 4300 S Lake Shore Dr

Inspector: Not applicable. See final comments below.

Date:

Time:

Site Conditions:

Days Since Last Rain Event:

### Final Comments

This site was included in the Metropolitan Planning Council's Green Infrastructure Baseline Inventory by the Chicago Department of Buildings as a bioinfiltration system, and site design indicates an infiltration trench in the vicinity of 41.817046°, -87.594515°. We were unable to locate the trench during a site visit in August, 2023 (photo below).



